



## Amspect Inspections LLC / MO. Home Energy Audits



Terry Clayton  
808 Fox Chase Dr.  
Arnold, MO 63010  
C-314-780-5250

# Energy Audit

**Infrared Images and Blower door Depressurized**

---


**Sample Report.**



**Visible Light Image**

**IR000494.IS2**

Possibly improperly installed insulation and or rodent activity.



**Visible Light Image**

**IR000496.IS2**

Top plate air leakage.